

Slide Rod Lubrication:

If you are experiencing lift chatter or pulse- it is most probably due to lack of lubrication. The slide rods should be lubricated once a day for best performance.



There are many lubrication points on any camera dolly- on ours, the slide rods are most important.

Weather conditions influence grease performance. Here is a list of acceptable greases you may find more suitable:

Lubriplate Multi-Purpose Lithium #630-2

Lubriplate Special Auto Marine #L0206-098

Kleen-Flo White Grease #909

CRC-Sta-Lube Super White #SL3150

Amrep Misty Lithium Complex EP Superfilm #G00733



Thoroughly clean the slide rods and move the lift up and down to expose any dirt or debris. Dispose of the soiled wipe properly. Afterwards- give each side 1 shot of grease.